



Forane® 408A

Pressure-Temperature Chart

Saturation Temperature [°F]	Liquid Pressure [psig]
-50	1.6
-45	1.1
-40	3.3
-35	5.6
-30	8.2
-25	11.1
-20	14.1
-15	17.5
-10	21.2
-5	25.2
0	29.5
5	34.2
10	39.3
15	44.8
20	50.7
25	57.0
30	63.7
35	71.0
40	78.7
45	87.0
50	95.8
55	105.1
60	115.1
65	125.6
70	136.8
75	148.7
80	161.2
85	174.4
90	188.4
95	203.1
100	218.7
105	235.4
110	252.1
115	270.2
120	289.1
125	308.9
130	329.7
135	351.5
140	374.3
145	398.1
150	423.0

Red numerals = inches Hg below 1 atm