



Forane® 22

Pressure-Temperature Chart

Saturation
Temperature Pressure
[°F] [psig]

-50	6.2
-45	2.7
-40	0.5
-35	2.6
-30	4.9
-25	7.4
-20	10.1
-15	13.2
-10	16.5
-5	20.0
0	23.9
5	28.2
10	32.8
15	37.7
20	43.0
25	48.7
30	54.9
35	61.5
40	68.5
45	76.0
50	84.0
55	92.5
60	101.6
65	111.2
70	121.4
75	132.2
80	143.6
85	155.7
90	168.4
95	181.8
100	195.9
105	210.7
110	226.3
115	242.7
120	259.9
125	277.9
130	296.8
135	316.5
140	337.2
145	358.8
150	381.5

Red numerals = inches Hg below 1 atm