



Forane® 407C

Pressure-Temperature Chart

Saturation Temperature [°F]	Liquid Pressure [psig]	Vapor Pressure [psig]
-50	-2.9	-11.4
-45	0.4	-8.5
-40	2.5	-5.2
-35	4.8	-1.5
-30	7.3	1.3
-25	10.1	3.6
-20	13.1	6.1
-15	16.5	8.8
-10	20.1	11.9
-5	24.0	15.2
0	28.3	18.9
5	33.0	22.9
10	38.0	27.3
15	43.5	32.0
20	49.3	37.2
25	55.7	42.7
30	62.5	48.7
35	69.8	55.2
40	77.6	62.1
45	86.0	69.5
50	94.9	77.5
55	104.5	86.0
60	114.6	95.1
65	125.4	104.8
70	136.9	115.2
75	149.1	126.2
80	162.1	137.8
85	175.8	150.2
90	190.2	163.4
95	205.5	177.4
100	221.6	192.1
105	238.5	207.8
110	256.4	224.4
115	275.1	241.9
120	294.7	260.5
125	315.2	280.1
130	336.7	300.9
135	359.2	322.9
140	382.6	346.2
145	407.0	370.8
150	432.4	396.9

Red numerals = inches Hg below 1 atm